




After implementations process of third floor of Garowe office in
Puntland state of Somalia




After implementation status of the boundary wall




Back side elevation of the watch tower
(inside the compound view)




Cross section A-A of the watch tower




Cross section B-B of the watch tower




Cross section C-C of the watch tower




Cross section D-D of the watch tower



Cross section E-E of the office building



Cross section F-F security room and toilet of UNCC Garowe.



Current cross section G-G of the temporary kitchen and cleaner ladies resting room of UNCC Garowe.