



Annex XII - a. Survey & assessment with identification of collapsed portions

Annex XII.a.1 - Al-Tahera Syriac Catholic Church- Roof Plan





Annex XII.a.2 - Al-Tahera Syriac Catholic Church- Section A-A.





Annex XII.a.3 - Al-Tahera Syriac Catholic Church- Section B-B.

The eastern elevation is quite intact; however, major collapses occurred on roof and underneath vaulted ceilings




Annex XII.a.4 - Al-Tahera Syriac Catholic Church- Section D-D.


Complete destruction of the southern side with subsequent collapse of the domes, roof and underneath vaulted ceilings




Annex XII.a.5 - Al-Tahera Syriac Catholic Church - Section C-C.







Complete destruction of the southern side with subsequent collapse of the domes, roof and underneath vaulted ceilings




Annex XII.a.6 - Al-Tahera Syriac Catholic Church - Section E-E.








SECTION BB



SECTION CC



SECTION FF




SECTION BB




SECTION CC




SECTION FF




SECTION DD




SECTION HH



SECTION EE




SECTION DD




SECTION HH



SECTION EE



SECTION GG




SECTION PP





SECTION GG



SECTION PP

