


e.1. View of the external fences – west and south elevations from the south-western corner





e.2. View of the southern side of the external fence






e.3. View of the western side of the external elevation





e.4. View of south-eastern corner of the annexed cloister







e.5. View of the southern elevation of the Church (currently completely collapsed)



e.6. View of external alley located along the southern side of the annexed cloister. View towards east







e.7. View the eastern elevation of the annexed cloister, from the south-eastern corner






e.8. View of main nave towards the northern side





e.9. View of the main nave towards east





e.10. View of the main nave towards west





e.11. View of the main nave towards south





e.12. View of the only remaining portion of the southern elevation, corresponding to the western side







e.13. View of the annexed cloister towards north





e.14. View of the annexed cloister towards west





e.15. View of the annexed cloister towards south





e.16. View of the annexed cloister towards east






e.17. View of the main entrance towards west





e.18. View of the main entrance towards north







e.19. View of main entrance towards south





e.20. View of the south-eastern corner of the annexed cloister





e.21. View of north-eastern corner of the complex.